





LEFT ELEVATION



PERSPECTIVE RIGHT FRONT



After



After



(Before)



After



Side showing stairs + deck  
will be almost completely  
obscured from view  
(Before)



Rear, 1402 showing rotten, sawed  
and broken rafters  
(Before)



After



Side 1402 showing 6"  
drop in porch - wrong  
direction  
(Before)



Another side view 1402 showing poor roof  
structure + badly sunken porch  
(Before)



Other side rear 1402 Showing broken, crooked & sawed rafters

Before



Rear 1402 Showing poor const. rear porch & sawed rafters plus crooked construction

Before




Before

NOTE RAFTER ALL SAWED OFF / OTHERS ROTTED  
KNOTE roof line




Rear 1402 Before



Before

CLOSE UP ends of rotted rafters-1402



1402 Rear  
Porch not says badly

Before



Side 1402, Porch structure

Before



Before



Before



Rear 1402 showing ends "skewed" & bad cond.

Before



PLEASE RETURN TO L. J. MALLICOTE - BRISTOL


Before



Before



STOFFER  
Graphic Arts



1

2

3

4

5

6

7

8

9

10



Handrails + stringers in place  
in attic. All tagged.



Treads, risers, newell posts  
and pickets in storage area  
in attic. All tagged.